

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
 690 Walnut Ave.St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.12**DAILY PROJECT JOURNAL****Prime Contractor:** American Bridge/Fluor Enterprises, a JV**Report No:** DPJ-000753**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Dated:** 23-Jul-2008**Location:** Changxing Island, Shanghai, China

Submittals(New / Total): **CWR's:** / **HSR's:** / **NCR's:** /

Item	Title	Detail
1	Other important observations	<p>On this date, SMR Chengwen Liu worked on swing shift at jobsite in Zhenhua Port Machinery Company facility on Changxing island, China.</p> <p>-- ZPMC started Corner Assembly at OBG assembly bay. Floorbeams and Bulkhead plates have been fit-up and tack welded to deck panel DP10A of Segment 3AE.</p> <p>-- ZPMC started fitting up side plates and bottom plate of Segment 5CE on OBG assembly bay, which is in line with Segment 3AE.</p>
2	Critical Weld Repairs (CWRs)	No CWRs were submitted during the swing shift on this date.
3	Heat Straightening Requests (HSRs)	No HSRs were submitted during the swing shift on this date.

Inspected By: Liu,Chengwen

Quality Assurance Inspector

Reviewed By: Velasco,Abifhiram

QA Reviewer